

General Environmental Incident Summary

Incident: 5853

Notice: 9/14/2018

Occurred: 9/13/2018

DEM Incident No:

No Further Action:

Responsible Party: Dakota Line Contractors

County: McKenzie

Twp Rng Sec Qtr: 152 98 34

Lat Long + Method: 47.94862 -103.20460 Interpolation from map

Location Description: From Watford City go north on HWY 1806 to 37th St NW. Go west approx. 1000' and then south on right of way 100'.

Submitted By Info: Kevin Berg
2729 Paintball Way
Bismarck ND

Received By Info:

Contact Info:
2729 Paintball Way
Bismarck ND

Affected Medium: 03 - soil

Near. Occupied Bldg:

Type of Incident: bore mud

Release Contained: Yes

Reported to NRC: Unknown

Contaminant: bentonite and water

Volume of Release:

Duration of Release:

Agriculture Related: No

EPA Extremely Hazardous Substance: No

Number of Fatalities:

Number of Injuries:

Cause of Incident:

Lost flow pulling bore pipe causing fluid to come to the surface.

Risk Evaluation:

none

Potential Env. Impacts:

none

Action Taken/Planned:

Spill was contained with straw wattles and cleaned up with a vac truck.

Wastes Disposal Location:

Other Agencies Involved:

Updates

Date: 9/14/2018 **Status:** Reviewed - No Action Required

Author: Stockdill, Scott

Notes:

According to the incident summary, this release impacted a small area and involved an inert substance. No follow-up is necessary.

Updated Volume: None at the time of this update