

General Environmental Incident Summary

Incident: 5854

Notice: 9/14/2018

Occurred: 9/14/2018

DEM Incident No:

No Further Action:

Responsible Party: Dakota Line Contractors

County: McKenzie

Twp Rng Sec Qtr: 152 98 34

Lat Long + Method: 47.94411 -103.20390 Interpolation from map

Location Description: From Watford City go north on HWY 1806 to 37th St NW. Go west approx. 1000', turn south onto right of way and go about 900'.

Submitted By Info: Kevin Berg
2729 Paintball Way
Bismarck ND

Received By Info:

Contact Info:
2729 Paintball Way
Bismarck ND

Affected Medium: 03 - soil

Near. Occupied Bldg:

Type of Incident: bore mud

Release Contained: Yes

Reported to NRC: Unknown

Contaminant: bentonite and water

Volume of Release: 30 gallons

Duration of Release: 10 minutes

Agriculture Related: No

EPA Extremely Hazardous Substance: No

Number of Fatalities:

Number of Injuries:

Cause of Incident:

Lost flow at machine causing down hole pressure and fluid came to the surface.

Risk Evaluation:

none

Potential Env. Impacts:

none

Action Taken/Planned:

silt fence and straw wattles were placed and spill was cleaned up with a vac truck.

Wastes Disposal Location:

Other Agencies Involved:

Updates

Date: 9/14/2018 **Status:** Reviewed - No Action Required

Author: Stockdill, Scott

Notes:

According to the incident summary, this release involved a small amount of an inert substance that was immediately cleaned up. No follow-up is necessary.

Updated Volume: None at the time of this update