

# General Environmental Incident Summary

**Incident:** 5856

**Notice:** 9/17/2018

**Occurred:** 9/15/2018

**DEM Incident No:**

**No Further Action:**

**Responsible Party:** Dakota Line Contractors

**County:** McKenzie

**Twp Rng Sec Qtr:** 152 98 22

**Lat Long + Method:** 47.96387 -103.20310 Interpolation from map

**Location Description:** From Watford City go north on HWY 1806 to 38 St NW. Go west approx. 1000' to right of way and 50' on the north side of the road.

**Submitted By Info:** Kevin Berg  
2729 Paintball Way  
Bismarck ND

**Received By Info:**

**Contact Info:**  
2729 Paintball Way  
Bismarck ND

**Affected Medium:** 03 - soil

**Near. Occupied Bldg:** 0.25 Miles

**Type of Incident:** bore mud

**Release Contained:** Yes

**Reported to NRC:** Unknown

**Contaminant:** bentonite and water

**Volume of Release:** 5 gallons

**Duration of Release:** 5 minutes

**Agriculture Related:** No

**EPA Extremely Hazardous Substance:** No

**Number of Fatalities:** 0

**Number of Injuries:** 0

**Cause of Incident:**

Lost returns to bore machine causing down hole pressure and fluids came to the surface.

**Risk Evaluation:**

none

**Potential Env. Impacts:**

none

**Action Taken/Planned:**

Silt fence was placed around the spill and cleaned up with a vac truck.

**Wastes Disposal Location:**

**Other Agencies Involved:**

## **Updates**

---

**Date:** 9/17/2018      **Status:** Reviewed - No Action Required

**Author:** Stockdill, Scott

**Notes:**

According to the incident summary, this release involved a small amount of an inert substance. No follow-up is necessary.

**Updated Volume:** None at the time of this update