

General Environmental Incident Summary

Incident: 5886 **Notice:** 10/18/2018 1818 **Occurred:** 10/18/2018 1400

DEM Incident No:

No Further Action:

Responsible Party: A&R Construction INC

County: Dunn

Twp Rng Sec Qtr: 140 94 18

Lat Long + Method: 47.47028 -102.70440 Calculated

Location Description: N killdeer, 104th st N to 4th st E. Marathon Leare RD

Submitted By Info: Nyomi Rodrigo
605 5th Ave SE
Dickinson ND 58601

Received By Info:

Contact Info: Nyomi Rodrigo
PO Box 2092
Dickinson ND 58602

Affected Medium: 03 - soil

Near. Occupied Bldg: 3 Miles

Type of Incident: Fraq Out

Release Contained: Yes

Reported to NRC: Unknown

Contaminant: water/subsoil mix

Volume of Release: 10 gallons

Duration of Release: 5 minutes

Agriculture Related: No

EPA Extremely Hazardous Substance: No

Number of Fatalities: 0

Number of Injuries: 0

Cause of Incident:

Fracced out

Risk Evaluation:

none

Potential Env. Impacts:

none

Action Taken/Planned:

cleaned up and no further frac out

Wastes Disposal Location:

exit hole

Other Agencies Involved:

Updates

Date: 10/18/2018 **Status:** Reviewed - No Action Required

Author: Stockdill, Scott

Notes:

According to the incident summary, this spill involved a small amount of inert material that was immediately cleaned up. No follow-up is necessary.

Updated Volume: None at the time of this update