

General Environmental Incident Summary

Incident: 5888 **Notice:** 10/23/2018 0745 **Occurred:** 10/22/2018 1830
DEM Incident No: **No Further Action:**
Responsible Party: Badlands Electric
County: McKenzie
Twp Rng Sec Qtr: 150 99 26
Lat Long + Method: 47.79007 -103.30560 Interpolation from map
Location Description: Intersection between 11th Ave. SW and 14th St. SW
Submitted By Info: Josh Breitbach
2222 124 T Ave. NW
Watford City ND 58854
Received By Info:
Contact Info: josh Breitbach
2222 124 T Ave. NW
Watford City ND 58854
Affected Medium: 03 - soil
Near. Occupied Bldg:
Type of Incident: hydrovac tank
Release Contained: Yes
Reported to NRC: Unknown
Contaminant: water and dirt mixture
Volume of Release: 200 gallons
Duration of Release: 10 minutes
Agriculture Related: No
EPA Extremely Hazardous Substance: No
Number of Fatalities:
Number of Injuries:
Cause of Incident: dumped hydrovac tank in wrong spot.
Risk Evaluation: none
Potential Env. Impacts: none
Action Taken/Planned: used hydrovac to suck mud back up out of road ditch.
Wastes Disposal Location: in appropriate mud pit.
Other Agencies Involved:

Updates

Date: 10/23/2018 **Status:** Reviewed - Follow-up Required

Author: Schiermeister, Robin

Notes:

Release, due to a driver error, was not contained. On onsite inspection is needed to determine the extent of damage.

Updated Volume: None at the time of this update

Date: 11/13/2018 **Status:** Inspection

Author: Martin, Russell

Notes:

11/7/2018 at 13:36, on location. Called report contact to confirm location, report contact described that mud from hydrovac lines across the street in the north & west ditch, was to be placed on dirt next to an electrical cabinet in the southwest corner ditch of the 11th St/14th St intersection. However, the hydrovac driver was concerned about trying to backup onto the dirt due to the proximity of a pipeline riser next to the cabinet, so instead, elected to empty the dirt into the vegetated portion of the ditch further to the west along 11th street (next to the old Watford City landfill). Checked area, light snow cover, but no visible mud on vegetation above or below the snow in the area indicated by the report contact, and marked by tire tracks in the vegetation. No further follow-up required at this time.

Updated Volume: None at the time of this update