# General Environmental Incident Summary

*Incident:* 5894 *Notice:* 11/2/2018 1010 *Occurred:* 11/2/2018 1000

DEM Incident No:

No Further Action:

Responsible Party: Park Construction

County: Mountrail
Twp Rng Sec Qtr: 150 93 4

Lat Long + Method: 47.84671 -102.58040 Navigation quality GPS
Location Description: The Sanish compressor site 9 miles south of New Town

Submitted By Info: Jaried Rise

Contractor HSE 12533 27th Ave NE Seattle WA 98125

Received By Info:

Contact Info: Tim Moe

1481 81st Ave NE

Minneapolis MN 55432

Affected Medium: 03 - soil Near. Occupied Bldg: 9 Miles

Type of Incident: Tank Overflow

Release Contained:YesReported to NRC:UnknownContaminant:Diesel fuelVolume of Release:10 gallons

Duration of Release: 1 minutes

Agriculture Related: No

**EPA Extremely** 

Hazardous Substance: Unknown

Number of Fatalities: 0
Number of Injuries: 0

Cause of Incident:

The trigger lock on a fuel pump nozzle stuck and failed to automatically disengage the pump nozzle. This resulted in the spill of 10 gallons of diesel fuel.

#### Risk Evaluation:

No immediate safety or health hazards

### Potential Env. Impacts:

Environmental impact unknown

#### Action Taken/Planned:

The soil was immediately dug down 1 foot below the spill with an excavator and the contaminated soil was loaded into a dump truck to be disposed of.

### Wastes Disposal Location:

#### Other Agencies Involved:

## **Updates**

Date: 11/2/2018 Status: Reviewed - Assigned to Other Agency

Author: O'Gorman, Brian

Notes:

According to the report, this incident occurred within MHA boundaries. Report forwarded to BIA,

MHA Environmental and EPA.

**Updated Volume:** None at the time of this update