## General Environmental Incident Summary

*Incident:* 5903 *Notice:* 11/9/2018 1234 *Occurred:* 11/8/2018 1445

DEM Incident No: No Further Action: ✓

Responsible Party:ConocoPhillipsCounty:McKenzieTwp Rng Sec Qtr:151 97 20

Lat Long + Method: 47.87676 -103.12250 Interpolation from map

Location Description: HE 1-20H

Submitted By Info: Joseph McLaughlin

ConocoPhillips 105 Prospect St.

Watford City ND 58854

Received By Info:

**Contact Info:** 

105 Prospect St.

Watford City ND 58854

Affected Medium: 03 - soil
Near. Occupied Bldg: 0.83 Miles
Type of Incident: Oil to flare

Release Contained: No

Reported to NRC: Unknown
Contaminant: Produced fluid

Volume of Release: 0.26 barrels

**Duration of Release:** 

Agriculture Related: No

**EPA Extremely** 

Hazardous Substance: Unknown

**Number of Fatalities:** 0 **Number of Injuries:** 0

Cause of Incident:

MSO was Driving by location and saw oil coming out of the flare. The MSO shut in the location and notified route MSO and area Supervisor, There was no Fire. Oil did leave location.

Risk Evaluation:

No risk to life and health

Potential Env. Impacts:

No anticipated risk to environment

Action Taken/Planned:

MSO shut in facility and notified supervisor. Work order has been submitted for cleanup.

Wastes Disposal Location:

Other Agencies Involved:

## **Updates**

Date: 11/13/2018 Status: Reviewed - Follow-up Required

Author: O'Gorman, Brian

Notes:

According to the report, 0.26 barrels of produced fluid was released from a flare and did leave the

location. Further follow-up needed.

Updated Volume: None at the time of this update

Date: 11/26/2018 Status: Inspection

Author: Schiermeister, Robin

## Notes:

Arrived on site at 9:58 on 11-20-2018. It was sunny with temperatures in the 20s. Walked around the flare and saw a slight discoloration to the grass west of the flare that could be from the release. There was also a dead area north of the site that could be from this release. A vegetation check will be needed next year in the spring. As a note, take 115th Ave NW and follow this road to the site.

Updated Volume: None at the time of this update

Date: 9/11/2019 Status: Inspection - Vegetation Check

Author: O'Gorman, Brian

## Notes:

Arrived on location at 8:51. 56 degrees F, Cloudy, Southeast wind 10-20 mph. Observed the site and took photos. It did not appear that the vegetation west and south of the flare had been impacted. It appeared healthy and had full coverage. Photos added to the incident folder. Recommend closing incident.

**Updated Volume:** None at the time of this update