

General Environmental Incident Summary

Incident: 5911 **Notice:** 11/21/2018 2020 **Occurred:** 11/20/2018 2045

DEM Incident No: **No Further Action:**

Responsible Party: Plains Marketing

County: Dunn

Twp Rng Sec Qtr: 147 96 25 SE

Lat Long + Method: 47.51690 -102.85000 Navigation quality GPS

Location Description: Around 12 miles northwest of Killdeer on Hwy 22 on west side of road.

Submitted By Info: Daniel Holli
P.O. Box 708
Belfield ND 58622

Received By Info:

Contact Info: Daniel Holli
P.O. Box 708
Belfield ND 58622

Affected Medium: 03 - soil

Near. Occupied Bldg: 1 Miles

Type of Incident: Truck overfill

Release Contained: Yes

Reported to NRC: No

Contaminant: Crude oil condensate

Volume of Release: 15 barrels

Duration of Release: 5 minutes

Agriculture Related: No

EPA Extremely Hazardous Substance: No

Number of Fatalities: 0

Number of Injuries: 0

Cause of Incident:

A contract Heart River trucking driver hauling oil for Plains Marketing overfilled his truck while loading.

Risk Evaluation:

None

Potential Env. Impacts:

Soil

Action Taken/Planned:

Contained oil condensate inside property. Contaminated soil is being excavated into rolloff boxes pending analysis prior to disposal.

Wastes Disposal Location:

Prairie Disposal

Other Agencies Involved:

Updates

Date: 11/23/2018 **Status:** Reviewed - Follow-up Required

Author: DeVries, Taylor

Notes:

According to the incident report, the release of oil was not contained. Further follow-up needed.

Updated Volume: None at the time of this update

Date: 12/27/2018 **Status:** Inspection

Author: Sandvick, Duane

Notes:

Weather Conditions: 48 degrees Fahrenheit - slight NW breeze - sunny skies

Time of Inspection: 12:10 pm MST on 12-18-2018

The department inspection detected no evidence of the spill was apparent. Photos were taken of the compressor station at the latitude/longitude given. No signs of impact after clean up. Closed the incident.

Updated Volume: None at the time of this update