

General Environmental Incident Summary

Incident: 5958

Notice: 1/17/2019 1443

Occurred: 1/17/2019

DEM Incident No:

No Further Action:

Responsible Party: BURLINGTON RESOURCES OIL & GAS COMPANY

County: McKenzie

Twp Rng Sec Qtr: 151 96 17 NW NW

Lat Long + Method: 47.90333 -103.00060 Navigation quality GPS

Location Description: DODGE 1-17H well pad. Spill occurred on south side of pad.

Submitted By Info: Kelsy Waggaman
11090 30th Street SW
Dickinson ND

Received By Info:

Contact Info:

925 N Eldridge
Houston TX

Affected Medium: 03 - soil

Near. Occupied Bldg:

Type of Incident: Oil to flare

Release Contained: No

Reported to NRC: No

Contaminant: Crude oil

Volume of Release:

Duration of Release:

Agriculture Related: No

EPA Extremely

Hazardous Substance: Unknown

Number of Fatalities: 0

Number of Injuries: 0

Cause of Incident:

Facility upset

Risk Evaluation:

N/A

Potential Env. Impacts:

Oil sheen observed on gravel pad and snow off-pad.

Action Taken/Planned:

COP personnel has visited facility and inspected flare. Flare confirmed to be in normal operation.

Wastes Disposal Location:

Other Agencies Involved:

Updates

Date: 1/17/2019 **Status:** Reviewed - Follow-up Required

Author: O'Gorman, Brian

Notes:

Release, due to oil to a flare, impacted an area off the well pad, according to the report. Further follow-up needed.

Updated Volume: None at the time of this update

Date: 1/23/2019 **Status:** Inspection

Author: Washek, Sandi

Notes:

Arrived onsite at 10:28am, weather was overcast with wind out of the west at 15 miles/hr. Temperature of 24 degrees F. The impacted area is located south of the flare into a cultivated field. You can see visible impacted snow still in the field. The area of impact is about 50 feet by 30 feet. GPS N47.90277 W103.00018 No visible oil on bare ground because the field is covered in snow. No water ways impacted. Area was not cleaned up at the time of the inspection. Additional follow-up needed.

Updated Volume: 1 barrels

Date: 8/6/2019 **Status:** Inspection

Author: Crowdus, Kory

Notes:

On location 8/6/2019, at 11:10am. Wheat field to the south of location is growing with no signs of remaining impacts. No further follow-up is required.

Updated Volume: None at the time of this update