

General Environmental Incident Summary

Incident: 6977 **Notice:** 2/6/2019 1100 **Occurred:** 2/5/2019 1015

DEM Incident No:

No Further Action:

Responsible Party: Beaver Creek, LLC

County: Mountrail

Twp Rng Sec Qtr: 151 93 30

Lat Long + Method: 47.87037 -102.62240 Interpolation from map

Location Description: From New Town head west to Sanish Road (92 Ave, 2nd St NW). Head south on Sanish Road for 9.5 miles to 30th street. Head right (west) on 30th street for 3 miles. Turn right (north) on lease road for 1.3 miles. Spill site occurred just after the cattle guard as the road bends to the left.

Submitted By Info: Barrett Withers
VP of Operations
9722 39th St NW
New Town ND 58763

Received By Info:

Contact Info: Barrett Withers
9722 39th St NW
New Town ND 58763

Affected Medium: 09 - other

Near. Occupied Bldg: 1 Miles

Type of Incident: Hose discharge

Release Contained: Yes

Reported to NRC: Unknown

Contaminant: Production Water

Volume of Release: 22 barrels

Duration of Release:

Agriculture Related: No

EPA Extremely

Hazardous Substance: Unknown

Number of Fatalities: 0

Number of Injuries: 0

Cause of Incident:

Around 1 am on 02/05 one of our trucks was stuck on the lease road. Another truck came to offload the stuck truck around 3 am in order to assist getting the truck unstuck. At approximately 10 AM we were notified that there was a spill between where the two trucks were transferring fluids.

Risk Evaluation:

The ground is frozen. We believe the only contamination that occurred was snow. We will conduct soil testing to ensure this is the case.

Potential Env. Impacts:

Possible Soil or surface water in the depression. This is currently frozen.

Action Taken/Planned:

The spill ran down the side of the lease road to a low spot (depression) where it is contained. We will be utilizing a hydrovac and skidsteer to remove the production water and snow.

Wastes Disposal Location:

Fluids will be filtered and disposed at approved Salt Water Disposal. Any contaminated soils will be

taken to approved solids disposal.

Other Agencies Involved:

Tribal

Updates

Date: 2/6/2019 ***Status:*** Reviewed - Assigned to Other Agency

Author: Schiermeister, Robin

Notes:

Release, due to a hose discharge, occurred within Fort Berthold. Location is within MHA Nation. Report forwarded to MHA Environmental, BIA and EPA. Tribe/BIA retain oversight.

Updated Volume: None at the time of this update