# General Environmental Incident Summary

*Incident:* 7006 *Notice:* 3/5/2019 *Occurred:* 3/4/2019 1330

DEM Incident No: No Further Action: ✓

Responsible Party: CHS Inc
County: Stutsman
Twp Rng Sec Qtr: 139 69

Twp Rng Sec Qtr: 139 69 1

Lat Long + Method: 46.87933 -99.33062 Interpolation from map

Location Description: Interstate 94 approx. 1/2 mile from Hwy 30 exit

Submitted By Info: Eric Pearson

CHS

4115 27th Ave N

Grand Forks ND 58201

Received By Info:

**Contact Info:** Eric Pearson

4115 27th Ave N Grand Forks ND

Affected Medium: 03 - soil

Near. Occupied Bldg:

Type of Incident: Tank Leak

Release Contained: Yes

Reported to NRC: Unknown
Contaminant: Dyed Diesel

Volume of Release: 15 gallons

Duration of Release: 15 minutes

Agriculture Related: Yes

**EPA Extremely** 

Hazardous Substance: No

Number of Fatalities: Number of Injuries: Cause of Incident:

Due to crash on 194 we had a small leak on tanker near top of tank. Unknown amount of Dyed Diesel leaked out of tanker on side of Interstate. Does not appear to be much product that leaked.

#### Risk Evaluation:

None

## Potential Env. Impacts:

Potential to ground

#### Action Taken/Planned:

At time of incident State Troopers cleared Interstate. will be heading back to site to get estimate on spill. Pumping off trailer will also estimate amount of product that may have leaked out.

#### Wastes Disposal Location:

If able to recover will dispose of properly

### Other Agencies Involved:

# **Updates**

Date: 3/5/2019 Status: Reviewed - Follow-up Required

Author: Crowdus, Kory

Notes:

Release on roadway or roadside ditch. Follow-up is required.

Updated Volume: None at the time of this update

Date: 3/26/2020 Status: Correspondence - More Follow-up Required

Author: DeVries, Taylor

Notes:

This incident will be inspected when a DEQ inspector goes east. Further follow-up is needed.

Updated Volume: None at the time of this update

Date: 5/21/2020 Status: Inspection - No Action Required

Author: Suess, Bill

Notes:

Visited the site on 5/20/2020. The vegetation looks healthy and consistent with the surrounding area. No further action is warranted.

Updated Volume: None at the time of this update