General Environmental Incident Summary

Incident: 7014 *Notice:* 3/11/2019 1036 *Occurred:* 3/11/2019 0930

DEM Incident No: No Further Action: ✓

Responsible Party: First Class Services

County: Cass

Twp Rng Sec Qtr: 139 49 4

Lat Long + Method: 46.87752 -96.88215 Interpolation from map

Location Description: Magellan Pipeline Company Fargo Terminal, 902 Main Avenue East, West

Fargo, ND

Submitted By Info: Tristan Grover

2503 SE 43rd Street

Des Moines IA 50327

Received By Info: IA - Iowa Grover

Contact Info:

9355 US 60 West

Lewisport KY 42351

Affected Medium: 09 - other

Near. Occupied Bldg:

Type of Incident: Semi Fuel Tank Leak

Release Contained: Yes
Reported to NRC: No

Contaminant: Diesel Fuel
Volume of Release: 2 gallons

Duration of Release: 10 minutes

Agriculture Related: No

EPA Extremely

Hazardous Substance: NoNumber of Fatalities: 0Number of Injuries: 0

Cause of Incident:

At 09:30 hours a transport driver was unloading butane at our facility when they noticed a pinhole leak in the transfer line between the transport's saddle tanks.

Risk Evaluation:

None as the spill was on concrete, was minimal in size, and immediately cleaned up.

Potential Env. Impacts:

None

Action Taken/Planned:

The release was stopped by the truck driver turning the truck off and cleaned up using absorbent pads and granular absorbent.

Wastes Disposal Location:

Absorbent materials will be disposed of with other facility waste through Heritage Environmental Services, our company approved waste disposal vendor.

Other Agencies Involved:

Local Law Enforcement, Local Emergency Manager

Updates

Date: 3/11/2019 Status: Correspondence

Author: Martin, Russell

Notes:

Phone call with driver of truck, personnel at terminal, and company that was initially reported as the responsible party (Farmers Oil Company). Farmers Oil indicated it was not them, but a related company, First Class Services. Report has been updated. Requested pictures of before/after cleanup of site from terminal personnel.

Updated Volume: None at the time of this update

Date: 3/11/2019 Status: Correspondence

Author: Martin, Russell

Notes:

Received photos of before/after cleanup at the site. No further follow-up required.

Updated Volume: None at the time of this update