

# General Environmental Incident Summary

**Incident:** 8071

**Notice:** 5/14/2019

**Occurred:** 5/14/2019

**DEM Incident No:**

**No Further Action:**

**Responsible Party:** Cargill, Inc.

**County:** Richland

**Twp Rng Sec Qtr:** 133 47 7

**Lat Long + Method:** 46.34691 -96.63818 Interpolation from map

**Location Description:** Cargill, Inc., 18049 County Rd 8E, Wahpeton, ND 58075

**Submitted By Info:** Josh Fritz  
18049 County Rd 8E  
Wahpeton ND

**Received By Info:**

**Contact Info:**  
18049 County Rd 8E  
Wahpeton ND

**Affected Medium:** 04 - water and soil

**Near. Occupied Bldg:**

**Type of Incident:** soda ash with water

**Release Contained:** Yes

**Reported to NRC:** Unknown

**Contaminant:** soda ash with water

**Volume of Release:**

**Duration of Release:**

**Agriculture Related:** No

**EPA Extremely Hazardous Substance:** Unknown

**Number of Fatalities:**

**Number of Injuries:**

**Cause of Incident:**

The soda ash slurry tank overflowed. Some of the material went to the floor and ran out of the slurry tank building outside to the parking area and to the ditch.

**Risk Evaluation:**

No immediate risk.

**Potential Env. Impacts:**

Material was dilute with no enviromental impact.

**Action Taken/Planned:**

Area was examined and a plan made to clean up. Spill is contained.

**Wastes Disposal Location:**

**Other Agencies Involved:**

## **Updates**

---

**Date:** 5/14/2019      **Status:** Reviewed - Follow-up Required

**Author:** Stockdill, Scott

**Notes:**

According to the incident summary, this spill impacted a small area with permeable ground. Follow-up by correspondence necessary.

**Updated Volume:** None at the time of this update

---

**Date:** 5/15/2019      **Status:** Correspondence

**Author:** Stockdill, Scott

**Notes:**

Photos taken by local public health officer show spill remained primarily to the parking lot and within the facility. Further impacts are unlikely. No follow-up is necessary.

**Updated Volume:** None at the time of this update