

General Environmental Incident Summary

Incident: 8080

Notice: 5/20/2019

Occurred: 5/18/2019 1250

DEM Incident No:

No Further Action:

Responsible Party: CHS Transportation

County: McLean

Twp Rng Sec Qtr: 148 84 8

Lat Long + Method: 47.64711 -101.41870 Interpolation from map

Location Description: Cenex Station 209 4th Ave SW Garrison ND

Submitted By Info: Eric Pearson
4115 27th Ave N
Grand Forks ND 58203

Received By Info:

Contact Info:
4115 27th Ave N
Grand Forks ND 58203

Affected Medium: 09 - other

Near. Occupied Bldg:

Type of Incident: Tank Overflow

Release Contained: Yes

Reported to NRC: Unknown

Contaminant: Dyed Diesel

Volume of Release: 10 gallons

Duration of Release: 1 minutes

Agriculture Related: Yes

EPA Extremely Hazardous Substance: No

Number of Fatalities:

Number of Injuries:

Cause of Incident:

Driver hooked into wrong FM Tank and overfilled tank. came out top. Stopped flow as soon as saw fuel come out top.

Risk Evaluation:

None. spill on concrete.

Potential Env. Impacts:

None material cleaned up immediately. Have pictures.

Action Taken/Planned:

applied floor dry and spill pads to concrete to contain spill. Shop from Minot sent person to assist in clean up of spill. all material taken up/cleaned up and back to shop.

Wastes Disposal Location:

Other Agencies Involved:

Updates

Date: 5/20/2019 **Status:** Reviewed - Follow-up Required

Author: Martin, Russell

Notes:

Release due to tank overflow, at a gas station according to the report. Follow-up is necessary. Called report contact and requested pictures of the cleanup and waste disposal information.

Updated Volume: None at the time of this update

Date: 5/20/2019 **Status:** Correspondence

Author: Martin, Russell

Notes:

Received photos of cleanup and disposal information. No further follow-up required.

Updated Volume: None at the time of this update