General Environmental Incident Summary

Incident: 8132 *Notice:* 6/26/2019 2200 *Occurred:* 6/26/2019 2000

DEM Incident No: No Further Action:

Responsible Party: Straight Line Directional LLC

County: McKenzie
Twp Rng Sec Qtr: 150 97 6

Lat Long + Method: 47.83403 -103.15380 Calculated

Location Description: 118th north of HWY 23. East of Watford City, ND

Submitted By Info: Ryan Olsen

2865 Finley St

Lincoln ND

Received By Info:

Contact Info:

5209 Sunlight Drive

Bismarck ND

Affected Medium: 03 - soil

Near. Occupied Bldg:

Type of Incident: Inadvertent Release

Release Contained: Yes
Reported to NRC: Unknown
Contaminant: Bentonite

Volume of Release:

Duration of Release:

Agriculture Related: No

EPA Extremely

Hazardous Substance: Unknown

Number of Fatalities:
Number of Injuries:
Cause of Incident:
Soft ground conditions
Risk Evaluation:
No immediate risk

Potential Env. Impacts:

No environmental impacts

Action Taken/Planned:

Contained with silt fence. Will clean up after bore is done

Wastes Disposal Location:

Other Agencies Involved:

Updates

Date: 6/26/2019 Status: Reviewed - Follow-up Required

Author: Biemiller, Richard

Notes:

Per report Bentonite release. Follow-up needed.

Updated Volume: None at the time of this update

Date: 7/5/2019 Status: Inspection

Author: Suess, Bill

Notes:

Visited the site on 7/3/2019. Bentonite mud has been cleaned up. Reclamation will occur with

reclaiming the pipeline corridor. No photos taken.

Updated Volume: None at the time of this update