

General Environmental Incident Summary

Incident: 8143 **Notice:** 7/2/2019 1345 **Occurred:** 7/2/2019 1300

DEM Incident No:

No Further Action:

Responsible Party: Magellan Pipeline Company, LP

County: Cass

Twp Rng Sec Qtr: 139 49 4

Lat Long + Method: 46.87746 -96.88187 Calculated

Location Description: Magellan Pipeline Company, LP
West Fargo Terminal
902 Main Avenue East
West Fargo, ND 58078

Submitted By Info: Laura Thompson
One Williams Center
Tulsa ND 74172

Received By Info:

Contact Info: Laura Thompson
902 Main Avenue East West
West Fargo ND 58078

Affected Medium: 09 - other

Near. Occupied Bldg:

Type of Incident: Pump Leak

Release Contained: Yes

Reported to NRC: Unknown

Contaminant: Hydraulic Fluid

Volume of Release: 0.5 gallons

Duration of Release: 1 minutes

Agriculture Related: No

EPA Extremely

Hazardous Substance: No

Number of Fatalities: 0

Number of Injuries: 0

Cause of Incident:

While off-loading, .5 gallons of hydraulic fluid was leaked from the offload pump in the biodiesel offload area. The leak originated from the o-ring on a quick connect for the pump.

Risk Evaluation:

None

Potential Env. Impacts:

None

Action Taken/Planned:

Pump was shutoff immediately and leak was contained.

Wastes Disposal Location:

Used absorbents will be disposed of properly through Heritage Environmental.

Other Agencies Involved:

NDDDES, Local Emergency Manager

Updates

Date: 7/3/2019 **Status:** Reviewed - Follow-up Required

Author: DeVries, Taylor

Notes:

According to the incident report, there was a release of 0.5 gallons of hydraulic fluid. Further follow-up is needed.

Updated Volume: None at the time of this update

Date: 2/14/2020 **Status:** Correspondence - No Action Required

Author: Suess, Bill

Notes:

Due to the volume and nature of the spill, no follow-up is needed. A final inspection of the site will be covered under General EIR #1330.

Updated Volume: None at the time of this update