

General Environmental Incident Summary

Incident: 8153

Notice: 7/12/2019

Occurred: 7/12/2019

DEM Incident No:

No Further Action:

Responsible Party: ONEOK

County: McKenzie

Twp Rng Sec Qtr: 151 97 28

Lat Long + Method: 47.87309 -103.11230 Navigation quality GPS

Location Description: Incident 2: 7/2/2019 3:00 PM 47.85510958-103.2621798S32 T151N R38W McKenzie Bentonite soil 5 gallons
Incident 3: 7/5/2019 2:35 PM 47.76072352-103.3911356S5 T149N R99W McKenzie transmission fluid Soil 4oz
Incident 4: 7/8/2019 2:30 PM 47.47467453-104.0037231S12 T146N R105W McKenzie Bentonite Soil 20 gallons

Submitted By Info: Edwin Zedaker
100 W Fifth St
Tulsa OK 74103

Received By Info:

Contact Info: Edwin Zedaker
100 West Fifth Street
Tulsa OK 74103

Affected Medium: 03 - soil

Near. Occupied Bldg:

Type of Incident:

Release Contained: Yes

Reported to NRC: Unknown

Contaminant: bentonite

Volume of Release:

Duration of Release:

Agriculture Related: No

EPA Extremely

Hazardous Substance: Unknown

Number of Fatalities:

Number of Injuries:

Cause of Incident:

Inadvertent return while performing an HDD in a vegetated upland

Risk Evaluation:

N/A

Potential Env. Impacts:

Low potential Environmental Impacts

Action Taken/Planned:

Drilling ceased upon noting pressure loss and the release was contained using silt fence and sand bags.

Wastes Disposal Location:

Other Agencies Involved:

Updates

Date: 7/12/2019 **Status:** Reviewed - Follow-up Required

Author: Crowdus, Kory

Notes:

Release at a non-exempt E&P facility. Follow-up is required.

Updated Volume: None at the time of this update

Date: 10/31/2019 **Status:** Inspection - Vegetation Check

Author: Washek, Sandi

Notes:

Arrived onsite with company rep.

Incident #2 was 5 gallons of bentonite in pastureland off of pipeline row located by and scoria pit.

Area has been cleaned of mud and the grass is visible in that area.

Incident #3 was 4 oz of transmission fluid located on pipeline row. Pipeline row has been leveled, no visible sign of stained soil.

Incident #4 is 20 gallons of bentonite mud located off pipeline row by the scoria pie in pastureland by directional bore. Area has been cleaned up.

Vegetation check needed.

Updated Volume: None at the time of this update

Date: 11/19/2020 **Status:** Inspection - No Action Required

Author: Suess, Bill

Notes:

Inspected all four sites on 11/17/2020. No adverse environmental impacts associated with this incident were observed. No further action is warranted.

Updated Volume: None at the time of this update