General Environmental Incident Summary

Incident: 8154 *Notice:* 7/12/2019 1200 *Occurred:* 7/11/2019 1700

DEM Incident No: No Further Action: ✓

Responsible Party: Quale Trucking, LLC

County: McKenzie

Twp Rng Sec Qtr: 151 96 24 NW NW NW

Lat Long + Method: 47.88938 -102.90620 Interpolation from map

Location Description: HA-Grimestad - LW -152-95-3031H-1

Submitted By Info: Rossco Chaffin

po box 970

New town ND 58763

Received By Info:

Contact Info: Rossco Chaffin

PO Box 970

New Town ND 58763

Affected Medium: 03 - soil
Near. Occupied Bldg: 1 Miles

Type of Incident: Vac Trailer leak

Release Contained: No

Reported to NRC: Unknown

Contaminant: Production Water

Volume of Release: 1.87 barrels

Duration of Release: 1 minutes

Agriculture Related: No

EPA Extremely

Hazardous Substance: Unknown

Number of Fatalities: 0
Number of Injuries: 0

Cause of Incident:

After loading the production water, the driver left location not knowing that he had a loose lid hatch and the water spilled out of this trailer hatch.

Risk Evaluation:

No immediate risk

Potential Env. Impacts:

Little environmental impact due to the fact water was released on dry gravel surface and impacted soil is being removed.

Action Taken/Planned:

Standing water was dried up with absorbent pads and the impacted gravel is being excavated out and hauled to disposal. Drivers are being reminded to check and tighten their hatch lids on trailers weekly.

Wastes Disposal Location:

TBD

Other Agencies Involved:

Updates

Date: 7/12/2019 Status: Reviewed - Follow-up Required

Author: Crowdus, Kory

Notes:

Release from a trailer leak. Follow-up is required.

Updated Volume: None at the time of this update

Date: 8/27/2019 Status: Inspection

Author: O'Gorman, Brian

Notes:

Arrived on location at 15:15. 64 degrees F, Mostly Cloudy, Northwest wind 20-30 mph. Drove to the well pad and took photos. Drove along lease road away from the well pad and took photos of the north and south sides of the lease road. Did not notice any dead and/or stressed vegetation in the ditch areas. No further follow-up needed at this time. Photos added to the incident folder.

Updated Volume: None at the time of this update