

General Environmental Incident Summary

Incident: 9219

Notice: 9/5/2019

Occurred: 9/2/2019

DEM Incident No:

No Further Action:

Responsible Party: Cass County Electric Coop

County: Barnes

Twp Rng Sec Qtr: 141 58 9

Lat Long + Method: 47.05121 -98.04368 Interpolation from map

Location Description: 2508 116TH AVE SE
VALLEY CITY, ND 58072

Submitted By Info: CJ Erickson

4100 32nd Ave S

FARGO ND 58104

Received By Info: ND - North Dakota Erickson

Contact Info: CJ Erickson

4100 32nd Ave S

FARGO ND 58104

Affected Medium: 03 - soil

Near. Occupied Bldg: 30 Feet

Type of Incident: Utility transformer spill from storm

Release Contained: Yes

Reported to NRC: Unknown

Contaminant: Transformer mineral oil, non-PCB per manufacture stamp on transformer

Volume of Release: 10 pounds

Duration of Release:

Agriculture Related: No

EPA Extremely

Hazardous Substance: Unknown

Number of Fatalities: 0

Number of Injuries: 0

Cause of Incident:

Overhead utility transformer was knocked down by a tree from a storm

Risk Evaluation:

None

Potential Env. Impacts:

oil contained and cleaned up

Action Taken/Planned:

Oil was contained and cleaned up using approved oil spill kit

Wastes Disposal Location:

Upon receipt of transformer oil testing, any non-PCB dirt and spill clean-up material will be disposed of at a land fill. If testing identifies the presents of PCB's measures will be taken to ensure disposal of all product is done through Clean Harbors Environmental, Inc., Coffeyville, KS.

Other Agencies Involved:

Updates

Date: 9/5/2019 **Status:** Reviewed - Assigned to NDDEQ Division

Author: O'Gorman, Brian

Notes:

According to the report, 10 pounds of non-PCB transformer oil was released during a storm. Further follow-up needed.

Updated Volume: None at the time of this update