## General Environmental Incident Summary

 Incident:
 9234
 Notice:
 9/16/2019
 1755
 Occurred:
 9/16/2019
 1345

DEM Incident No: No Further Action: ✓

Responsible Party: Wanzek Construction Inc

County: Williams

Twp Rng Sec Qtr: 156 100 33 SW SW SW

Lat Long + Method: 48.28607 -103.56120 Interpolation from map

Location Description: New compressor site location - East Fork Compressor Station, 60004 133rd

Ave NW, Williston, ND

Submitted By Info: Rodger Schmidt

Wanzek - Safety manager

4850 32nd Ave S Fargo ND 58104

Received By Info:

Contact Info: Rodger Schmidt

4850 32nd Ave S Fargo ND 58104

Affected Medium: 03 - soil

Near. Occupied Bldg:

Type of Incident: hydraulic line leak on equipment

Release Contained: Yes
Reported to NRC: No

**Contaminant:** hydraulic fluid

Volume of Release: 0.5 gallons

Duration of Release: 15 minutes

Agriculture Related: No

**EPA Extremely** 

Hazardous Substance: NoNumber of Fatalities: 0Number of Injuries: 0

Cause of Incident:

Hydraulic fitting cracked causing hydraulic fluid to be leaked.

Risk Evaluation:

N/A

Potential Env. Impacts:

None - All contaminated soil has been removed

Action Taken/Planned:

Contaminated soil was scooped up using hand shovels and containerized. Additional hydraulic oil during repair contained with absorbent pads and bagged. Additional potential spot cleanup required after equipment is moved from site.

Wastes Disposal Location:

Appropriate landfill - anticipated 13 Mile Disposal - Williston

Other Agencies Involved:

## **Updates**

Date: 9/16/2019 Status: Correspondence - No Action Required

Author: Crowdus, Kory

Notes:

Received email with photos of release and photos after cleanup. Photos added to report folder. No

further follow up required.

**Updated Volume:** None at the time of this update