

Updates

Date: 9/20/2019 **Status:** Reviewed - Follow-up Required

Author: Crowdus, Kory

Notes:

Release at gas station. Follow up is required. This station is just east of the Fort Berthold reservation boundary.

Updated Volume: None at the time of this update

Date: 9/26/2019 **Status:** Inspection - No Action Required

Author: Stockdill, Scott

Notes:

Arrived on location 10:45 9/26/2019.

Staining around pump area. No visible impacts to areas other than the area immediately by the pump.

No follow up is necessary.

Updated Volume: None at the time of this update