

General Environmental Incident Summary

Incident: 9247

Notice: 9/24/2019

Occurred: 9/20/2019

DEM Incident No:

No Further Action:

Responsible Party: ONEOK

County: McKenzie

Twp Rng Sec Qtr: 147 104 26

Lat Long + Method: 47.52072 -103.88630 Navigation quality GPS

Location Description: At the intersection of 68 and 16, head south on 16 for 13 miles. Signs indicating pipeline construction will be seen and the site is north of 16.

Submitted By Info: Edwin Zedaker
100 W Fifth St
Tulsa OK 74103

Received By Info:

Contact Info: Edwin Zedaker
100 W Fifth St
Tulsa OK 74103

Affected Medium: 03 - soil

Near. Occupied Bldg:

Type of Incident:

Release Contained: Yes

Reported to NRC: Unknown

Contaminant: bentonite

Volume of Release:

Duration of Release:

Agriculture Related: No

EPA Extremely Hazardous Substance: Unknown

Number of Fatalities:

Number of Injuries:

Cause of Incident:

Inadvertent Return

Risk Evaluation:

N/A

Potential Env. Impacts:

N/A

Action Taken/Planned:

Mud was cleaned up and disposed of

Wastes Disposal Location:

Other Agencies Involved:

Updates

Date: 9/24/2019 **Status:** Reviewed - Follow-up Required

Author: DeVries, Taylor

Notes:

According to the incident report there was a release of bentonite clay. Further follow up will be made with company on amount and if there were any additives.

Updated Volume: None at the time of this update

Date: 10/9/2019 **Status:** Inspection - More Follow-up Required

Author: DeVries, Taylor

Notes:

Received confirmation that the release was just bentonite and water. Inspection Date: 10/9/2019

Arrived on location at 1300. The release has been dug up due to active pipeline installation. No further follow up is needed at this time.

No photos were taken at the time of the inspection.

Updated Volume: None at the time of this update