## **General Environmental Incident Summary**

Incident: 0250	Nation 0/20/2010 0040 <b>O</b> ccurred 0/40/2010 4200
Incident: 9258 DEM Incident No:	<i>Notice:</i> 9/20/2019 0940 <i>Occurred:</i> 9/19/2019 1300 <i>No Further Action:</i> ✓
	Minot AFB
Responsible Party: County:	McLean
Twp Rng Sec Qtr:	149 85 14
Lat Long + Method:	47.71881 -101.51970 Interpolation from map
Location Description:	Approximately 0.5 miles west of intersection of 21st Street NW (Hwy 13)
Looution Description.	and 43rd Ave NW
Submitted By Info:	Douglas Janulewicz
	AFCEC
	106 Peacekeeper Drive
	Suite 2N3
	Offutt AFB NE 68113
Received By Info:	
Contact Info:	
	445 Peacekeeper Place
	Minot AFB ND 58705
Affected Medium:	03 - soil
Near. Occupied Bldg:	0.5 Miles
Type of Incident:	Hydraulic Hose on Crane
Release Contained:	Yes
Reported to NRC:	No
Contaminant:	Hydraulic Fluid
Volume of Release:	20 gallons
Duration of Release:	
Agriculture Related:	No
EPA Extremely Hazardous Substance:	No
Number of Fatalities:	0
Number of Injuries:	
Cause of Incident:	
Broken Hydraulic Hose o	on Crane
Risk Evaluation:	
None	
Potential Env. Impacts:	:
None	

## Action Taken/Planned:

A hydraulic hose on a crane broke while operating at E-03. Approximately 20 gallons of hydraulic fluid was released to the gravel hardpan. The spill was contained to an area approximately 4' by 3'. A pig mat was placed over the spill to absorb the fluid. The mat will be containerized, labeled, and transported to the HazMart at Minot AFB.

## Wastes Disposal Location:

The pig mat will be containerized, labeled, and transported to the HazMart at Minot AFB.

Other Agencies Involved:

## Updates

Date: 9/20/2019 Status: Reviewed - Assigned to NDDEQ Division

Author: Crowdus, Kory

Notes:

Report forwarded to the Division of Waste Management.

**Updated Volume:** None at the time of this update