General Environmental Incident Summary

Responsible Party: WBI Energy Transmission Inc.

County: McKenzie
Twp Rng Sec Qtr: 149 98 30

Lat Long + Method: 47.70304 -103.27980 Interpolation from map

Location Description: Drive 6.6 miles south of Watford City on HWY 85. Turn east on access

road to Spring Creek Measurement Facility.

Submitted By Info: Greg Huncovsky

2010 Montana Ave. Glendive MT 59330

Received By Info:

Contact Info: Greg Huncovsky

2010 Montana Ave Glendive MT 59330

Affected Medium: 03 - soil
Near. Occupied Bldg: 0.5 Miles
Type of Incident: Tank Leak

Release Contained: Yes

Reported to NRC: Unknown

Contaminant: Oil and hydrocarbon condensate

Volume of Release: 25 gallons

Duration of Release: 5 minutes

Agriculture Related: No

EPA Extremely

Hazardous Substance: Unknown

Number of Fatalities: 0
Number of Injuries: 0

Cause of Incident:

Dump valve stuck open. Possibly cold weather related.

Risk Evaluation:

none

Potential Env. Impacts:

none

Action Taken/Planned:

Liquids will be immobilized with floor dry or other equivalent dry material. Contaminated material will then be removed with an excavator or vac truck.

Wastes Disposal Location:

At an approved facility.

Other Agencies Involved:

Updates

Date: 11/13/2019 Status: Reviewed - Follow-up Required

Author: O'Gorman, Brian

Notes:

According to the report, 25 gallons of oil and condensate were released at the Spring Creek facility.

More follow-up needed.

Updated Volume: None at the time of this update

Date: 11/18/2019 Status: Inspection - No Action Required

Author: Schmitt, Bryan

Notes:

Inspection Date: 11/14/2019

Time: 2:15 pm CT

Temp: 46F

I walked the site and did not find any remaining impacts from this spill. I believe the contamination was cleaned up and removed. Pictures taken.

Updated Volume: None at the time of this update