

General Environmental Incident Summary

Incident: 9398

Notice: 2/10/2020

Occurred: 2/6/2020 1800

DEM Incident No:

No Further Action:

Responsible Party: CHS Transportation

County: Steele

Twp Rng Sec Qtr: 145 56 36

Lat Long + Method: 47.32700 -97.73323 Interpolation from map

Location Description: 13185 6th St se

Submitted By Info: Eric Pearson
4115 27th Ave N
Grand Forks ND

Received By Info:

Contact Info:
4115 27th ave N
Grand Forks ND

Affected Medium: 03 - soil

Near. Occupied Bldg:

Type of Incident: Tank Overflow

Release Contained: Yes

Reported to NRC: Unknown

Contaminant: Dyed Diesel

Volume of Release: 20 gallons

Duration of Release: 1 minutes

Agriculture Related: Yes

EPA Extremely Hazardous Substance: No

Number of Fatalities:

Number of Injuries:

Cause of Incident:

Driver ran fuel into wrong tank and overflowed. shut down immediately but some product sprayed over concrete dyke onto gravel.

Risk Evaluation:

None...cleaned up from frozen ground

Potential Env. Impacts:

None...cleaned up from frozen ground

Action Taken/Planned:

Area outside containment was cleaned up with Floor dry and spill pads the next morning. gravel scraped until no dyed fuel was seen. Inside of containment will be cleaned and disposed of by OSI Environmental.

Wastes Disposal Location:

Disposed of by OSI Environmental.

Other Agencies Involved:

Updates

Date: 2/10/2020 **Status:** Reviewed - Follow-up Required

Author: Suess, Bill

Notes:

Incident involves refined petroleum. Follow-up is needed.

Updated Volume: None at the time of this update

Date: 2/10/2020 **Status:** Correspondence - No Action Required

Author: Schiermeister, Robin

Notes:

Received pictures confirming the release was cleaned up. No further follow up is necessary at this time. The email with the pictures has been added to the incident folder.

Updated Volume: None at the time of this update