

General Information

Total Number of UST Facilities: 833 Public Record Posted Date: 10/02/2023
 Total Number of USTs: 2207 Reporting Period Dates: 10/01/2022 to 09/30/2023

Summary Information For On-Site Inspections

Criteria

Number of UST Facilities Inspected: 309 Indian Lands: False
 Percent Compliance: 34.58%

Summary Information For Release

Number of Confirmed UST Releases: 3

Summary Information For Release Sources and Causes

Source			Cause													
			Spill		Overfill		Phy/Mech Damage		Corrosion		Install Problem		Other		Unknown	
#	%		#	%	#	%	#	%	#	%	#	%	#	%	#	%
Tank	3	60.0	1	100.0	1	100.0	0	0.0	1	50.0	0	0.0	0	0.0	0	0.0
Piping	2	40.0	0	0.0	0	0.0	1	100.0	1	50.0	0	0.0	0	0.0	0	0.0
Dispenser	0	0.0	0	0.0	0	0.0	0	0.0	0	0.0	0	0.0	0	0.0	0	0.0
STP	0	0.0	0	0.0	0	0.0	0	0.0	0	0.0	0	0.0	0	0.0	0	0.0
Delivery Problem	0	0.0	0	0.0	0	0.0	0	0.0	0	0.0	0	0.0	0	0.0	0	0.0
Other	0	0.0	0	0.0	0	0.0	0	0.0	0	0.0	0	0.0	0	0.0	0	0.0
Totals	5	100.0	1	100.0	1	100.0	1	100.0	2	100.0	0	0.0	0	0.0	0	0.0

= Number of releases
 % = Percent of total number of Source

Note: Release, sources and causes information are based on USTs as defined in NDAC Section 33.1-24-08-40. Source and cause data is collected from information provided through release reporting as required in NDAC Section 33.1-24-08-40. Site specific UST information on compliance and releases can be obtained upon request.