

General Information

Total Number of UST Facilities: 827 Public Record Posted Date: 10/01/2019
 Total Number of USTs: 2228 Reporting Period Dates: 10/01/2018 to 09/30/2019

Summary Information For On-Site Inspections

Criteria

Number of UST Facilities Inspected: 249 Indian Lands: False
 Percent Compliance: 81.97%

Summary Information For Release

Number of Confirmed UST Releases: 3

Summary Information For Release Sources and Causes

Source			Cause													
			Spill		Overfill		Phy/Mech Damage		Corrosion		Install Problem		Other		Unknown	
	#	%	#	%	#	%	#	%	#	%	#	%	#	%	#	%
Tank	3	50.0	0	0.0	0	0.0	0	0.0	0	0.0	0	0.0	0	0.0	3	50.0
Piping	3	50.0	0	0.0	0	0.0	0	0.0	0	0.0	0	0.0	0	0.0	3	50.0
Dispenser	0	0.0	0	0.0	0	0.0	0	0.0	0	0.0	0	0.0	0	0.0	0	0.0
STP	0	0.0	0	0.0	0	0.0	0	0.0	0	0.0	0	0.0	0	0.0	0	0.0
Delivery Problem	0	0.0	0	0.0	0	0.0	0	0.0	0	0.0	0	0.0	0	0.0	0	0.0
Other	0	0.0	0	0.0	0	0.0	0	0.0	0	0.0	0	0.0	0	0.0	0	0.0
Totals	6	100.0	0	0.0	0	0.0	0	0.0	0	0.0	0	0.0	0	0.0	6	100.0

= Number of releases
 % = Percent of total number of Source

Note: Release, sources and causes information are based on USTs as defined in NDAC Section 33.1-24-08-40. Source and cause data is collected from information provided through release reporting as required in NDAC Section 33.1-24-08-40. Site specific UST information on compliance and releases can be obtained upon request.