

General Information

Total Number of UST Facilities: 834 Public Record Posted Date: 10/01/2025
 Total Number of USTs: 2217 Reporting Period Dates: 10/01/2024 to 09/30/2025

Summary Information For On-Site Inspections

Criteria

Number of UST Facilities Inspected: 233 Indian Lands: False
 Percent Compliance: 49.33%

Summary Information For Release

Number of Confirmed UST Releases: 5

Summary Information For Release Sources and Causes

Source			Cause													
			Spill		Overfill		Phy/Mech Damage		Corrosion		Install Problem		Other		Unknown	
	#	%	#	%	#	%	#	%	#	%	#	%	#	%	#	%
Tank	1	7.7	0	0.0	0	0.0	0	0.0	0	0.0	0	0.0	0	0.0	1	11.1
Piping	4	30.8	1	33.3	0	0.0	0	0.0	0	0.0	0	0.0	0	0.0	3	33.3
Dispenser	2	15.4	0	0.0	0	0.0	1	100.0	0	0.0	0	0.0	0	0.0	1	11.1
STP	1	7.7	0	0.0	0	0.0	0	0.0	0	0.0	0	0.0	0	0.0	1	11.1
Delivery Problem	1	7.7	0	0.0	0	0.0	0	0.0	0	0.0	0	0.0	0	0.0	1	11.1
Other	4	30.8	2	66.7	0	0.0	0	0.0	0	0.0	0	0.0	0	0.0	2	22.2
Totals	13	100.0	3	100.0	0	0.0	1	0.0	0	0.0	0	0.0	0	0.0	9	100.0

= Number of releases
 % = Percent of total number of Source

Note: Release, sources and causes information are based on USTs as defined in NDAC Section 33.1-24-08-40. Source and cause data is collected from information provided through release reporting as required in NDAC Section 33.1-24-08-40. Site specific UST information on compliance and releases can be obtained upon request.