

General Information

Total Number of UST Facilities: 832 Public Record Posted Date: 10/11/2021
 Total Number of USTs: 2211 Reporting Period Dates: 10/01/2020 to 09/30/2021

Summary Information For On-Site Inspections

Criteria

Number of UST Facilities Inspected: 337 Indian Lands: False
 Percent Compliance: 47.06%

Summary Information For Release

Number of Confirmed UST Releases: 5

Summary Information For Release Sources and Causes

Source			Cause													
			Spill		Overfill		Phy/Mech Damage		Corrosion		Install Problem		Other		Unknown	
#	%		#	%	#	%	#	%	#	%	#	%	#	%	#	%
Tank	5	20.8	1	50.0	0	0.0	0	0.0	0	0.0	0	0.0	0	0.0	4	23.5
Piping	15	62.5	1	50.0	5	100.0	0	0.0	0	0.0	0	0.0	0	0.0	9	52.9
Dispenser	1	4.2	0	0.0	0	0.0	0	0.0	0	0.0	0	0.0	0	0.0	1	5.9
STP	1	4.2	0	0.0	0	0.0	0	0.0	0	0.0	0	0.0	0	0.0	1	5.9
Delivery Problem	1	4.2	0	0.0	0	0.0	0	0.0	0	0.0	0	0.0	0	0.0	1	5.9
Other	1	4.2	0	0.0	0	0.0	0	0.0	0	0.0	0	0.0	0	0.0	1	5.9
Totals	24	100.0	2	100.0	5	100.0	0	100.0	0	0.0	0	0.0	0	0.0	17	100.0

= Number of releases
 % = Percent of total number of Source

Note: Release, sources and causes information are based on USTs as defined in NDAC Section 33.1-24-08-40. Source and cause data is collected from information provided through release reporting as required in NDAC Section 33.1-24-08-40. Site specific UST information on compliance and releases can be obtained upon request.